

Betroffene Vesper Modelle:

Base: 52041, 52042, 5204 High Base: 52044, 52045, 52046 Double: 52047, 52048, 52049



Bei den V – Tubes hat es eine technische Änderung der Gewinde an beiden Enden der Röhren gegeben.

Die neuen Gewinde, die benötigten Schrauben und die Verbinder sind größer als die bisher verwendeten und nicht kompatibel.

Ein Mischverbau von alten und neuen V-Tubes ist auf Grund von verschiedenen Gewindegrößen nicht möglich, d.h. die V-Tubes können nur paarweise getauscht werden.



✓ Neue Schraube



✗ Bisherige Schraube



Schraubenset 52205

Verwenden Sie in diesem Fall das Schraubenset 52205 !

Bohrer 8mm
 (nicht im Lieferumfang)



Bohrungen für die Schrauben im Holz müssen ggf. auf 8mm aufgebohrt werden.

Vesper model:

V-Base: 52041, 52042, 5204 V-High Base: 52044, 52045, 52046 V-Double: 52047, 52048, 52049



There is a technical change for the threads on both ends of the tubes.

The new threads, the needed screws and the connectors are bigger than the previous ones and ***incompatible***.

A miscibility of old and new Tubes is not possible because of different thread sizes, following the tubes can only be exchanged in pairs.



✓ New screw



✗ Previous screw



Screwset 52205

Use screw set 52205 in this case.

Drill 8mm
(not included)



Drillings in the wood for screws may have to be enlarged to 8mm.